



## END OF LIFE NOTIFICATION

|                     |  |
|---------------------|--|
| <b>Title</b>        | Discontinuance of TCE4 and TCF4 TCXO Series  |
| <b>Article:</b>     | <p><b><u>Products Affected:</u></b> Pletronics TCE4, 3.2x2.5 – TCF4, 2.5x2 TCXO Series</p> <p><b><u>Reason:</u></b> This product is being discontinued due to discontinuation of the integrated circuits.</p> <p><b><u>Alternative Sources:</u></b> Pletronics recommends the UCE4, 3.2x2.5 and UCF4, 2.5x2 series as replacement series. There are minor difference between the series, so PLE advises reviewing the data sheet for compatibility. Please contact Pletronics for specific questions.</p> <p><b><u>Issue Date:</u></b> 10/11/18</p> <p><b><u>Last Purchase Date:</u></b> 2-01-2019</p> <p><b><u>Updated 12-09-2020:</u></b> Changed the recommended replacement series from NCE4 and NCF4 to UCE4 and UCF4</p> |
| <b>Date Created</b> | 10/11/18   |
| <b>Created By</b>   | Pletronics Engineering<br><a href="mailto:Ple-eng-mfg@pletronics.com">Ple-eng-mfg@pletronics.com</a>   |