

## **END OF LIFE NOTIFICATION**

**Title** Discontinuance of TCD4, TCD3, THD4, THD3, TCA3, TCA4, THA3, TSA4,

TCA1, THA1, THA4, TBA4 Series

Article: Products Affected: Pletronics TCD4, TCD3, THD4, THD3, TCA3, TCA4,

THA3, TSA4, TCA1, THA1, THA4, TBA4 Series

Reason for Discontinuance: The AKM factory fire disrupted the global supply chain of TCXO/VCTCXO product. AKM has reduced their offering of IC's as they try to return to normal business. The IC's used in these TCXO/VCTCXO product lines have been discontinued. Available products are limited to existing stock.

<u>Suggested Replacement Part</u>: UCD4 and UHD4 (5.0x3.2mm). For 5.0x7.0mm packages please contact Pletronics for suggested replacement.

**Issue Date**: 7-01-2021

**Last Purchase Date:** 

Limited to available inventory.

**Date Created** 7-01-2021

Created By Pletronics Engineering

**Rev** 1.0