



Title Discontinuance of VPB7 series

Article: **Products Affected:** Pletronics VPB7 Differential Oscillator Series.

Reason for Discontinuance: VPB7 series is based on older IC technology. The products is being discontinued due to the increased cost of manufacturing and support.

Suggested Replacement Part: The recommended replacement product is the QP77L series. The QP77L series is a standard 7x5mm package.

Issue Date: 6-15-2020

Last Purchase Date: 9-30-2020

There may be limited supplies available.

Last Shipment Date: 12-31-2020

Pletronics Inc. certifies this device is in accordance with the RoHS (2015/65/EC) and WEEE (2002/96/EC) directives.

Date Created 6-15-2020

Created By Pletronics Engineering

Rev 1.0