

END OF LIFE NOTIFICATION

Title	Discontinuance of LV77K, PE77K, LV55K and PE55K Series
Article:	<u>Products Affected:</u> Pletronics LV55K/LV77K and PE55K/PE77K, Differential Oscillator Series <u>Reason:</u> The IC used is obsolete lv77k 3.3v.pdf (pletronics.com) lv77k 2.5v.pdf (pletronics.com) lv55k 3.3v.pdf (pletronics.com) lv55k 2.5v.pdf (pletronics.com) pe77k 3.3v.pdf (pletronics.com) pe77k 2.5v.pdf (pletronics.com) pe55k 3.3v.pdf (pletronics.com) pe55k 2.5v.pdf (pletronics.com) <u>Recommended Replacement:</u> For Fit/form/closest function: 7050 size - LV77J/PE77J lv77j 3.3v.pdf (pletronics.com) lv77j 2.5v.pdf (pletronics.com) pe77j 3.3v.pdf (pletronics.com) pe77j 2.5v.pdf (pletronics.com) 5032 size - LV55J/PE55J lv55j 3.3v.pdf (pletronics.com) lv55j 2.5v.pdf (pletronics.com) pe55j 3.3v.pdf (pletronics.com) pe55j 2.5v.pdf (pletronics.com) For downsize to 3225: LVDS - LV44J and PECL – PE44J lv44j 3.3v.pdf (pletronics.com) lv44j 2.5v.pdf (pletronics.com) pe44j 3.3v.pdf (pletronics.com) pe44j 2.5v.pdf (pletronics.com) Please contact Pletronics for specific questions. <u>Issue Date:</u> 12/20/21 <u>Last Purchase Date:</u> Limited to available stock
Date Created	12/20/21
Created By	Pletronics Engineering Ple-eng-mfg@pletronics.com